

# ELSK01 Leaf Spring Service Kit Clip liner kit to suit EL springs

## HAND TOOLS & LUBRICANTS REQUIRED

Leaf spring removal tools, 14mm Spanner, hacksaw, vice grips, G-clamp & TB1001

#### **KIT CONTENTS**

ITEMPART NUMBERDESCRIPTIONELSK01ELCL100CLIP LINER EL SPRING 100MM

**QTY** 6

#### LEAF SPRING PREPARATION

- 1. Remove the leaf spring from the vehicle.
- 2. Remove all the U-clip retaining bolts as shown.

 To disassemble the leaf spring ensure the spring is well secured with a clamp before releasing the centre spring bolt as shown. Use vice grips to secure the round head of the centre bolt if required.







4. Separate each leaf spring as shown.



## **CLIP LINER FITMENT**

If the spring is fitted with a rubber liner then the liner will need to be replaced with a plastic clip liner.

1. Identify the leafs that have U-clips attached. To remove the existing rubber liners use a hack saw as shown.

2. Ensure that all of the rubber is removed, use a chisel if any rubber remains.







- 3. Refer to Table 1 for clip liner lengths to suit your leaf spring. Cut the clip liner material using a hack saw or similar.
- Push the clip liner over the clip and right to the bottom as shown. Grease the face of the clip using TB1001.



### LEAF SPRING ASSEMBLY

While the spring is apart check the condition of the yellow inter-leaf liners. Replace inter-leaf liners (Emu Leaf Service Kit No. ELSK02) at this stage if required.

If the spring is not fitted with 1.6mm thick steel inter-leaf spacers at the centre bolt consider adding these spacers at this stage. These spacers are found in ELSK03 (for 60mm wide springs) or ELSK04 (for 70mm wide springs).

Assemble the leaf spring back together with the inter-leaf plates using the centre bolt to align each item. Pull the leaf pack together with a clamp and fasten the centre bolt nut. Be careful not to overtighten the U-Clip bolts as the individual leafs need to move freely between the U-Clip liners. Before re-fitting the leaf spring apply grease (Part No. TB1001), to all bush faces and inserts.

The leaf spring has now been serviced with new U-Clip liners and is ready to be fitted to the vehicle.







## **TABLE 1: CLIP LINER LENGTHS**

Vehicle	Spring No.	U-Clip insert length (mm)	Quantity
	51.0.420	60	4
	EL043R	50	2
		60	4
111 2005	ELU44R	R   60     R   60     R   50     R   60     R   50     R   50     R   70     R   50     R   70     R   60     R   70     R   60     R   70     R   60     R   60     R   60     R   60     R   60     R   80     R   60     R   80     R   50     R   80     R   90     R   70     R   70     R   90     R   100     R   100     R   90     90	2
Hilux 2005			4
	ELU45R	50	2
	EL071R	70	4
		50	2
	EL 000D	50 70 60 70 80 70 60 60 60 80 50	4
Hilux 2015 on	ELU89R	70	2
	EL090R	60	4
		70	2
	510045	80	4
	EL091R	70	2
	EL049R	60	4
Ranger 2006 on	EL068R	60	4
0	EL069R	80	4
	EL072R	50	2
		80	2
		50	4
DMAX/ Colorado	ELU73R	L044R     60       L045R     50       L071R     70       L071R     50       L089R     70       L090R     60       L090R     70       L090R     70       L090R     60       L091R     70       L045R     60       L091R     70       L049R     60       L068R     60       L069R     80       L072R     50       L073R     50       L074R     70       L074R     70       L083R     90       L083R     90       L084R     100       L092R     70       90     90       L093R     90       L093R     90       L094R     90	2
	o EL073R EL074R	70	4
	EL074R	50     60     50     60     50     70     50     70     60     70     60     70     60     70     60     70     60     70     80     70     80     70     80     70     80     70     80     70     80     70     80     70     80     70     80     70     90     80     70     90     80     100     80     100     80     100     90     90     90     90     90     90     90     90     90 </td <td>2</td>	2
	51 00 2 5	60     50     60     50     60     50     70     50     70     50     70     60     70     60     70     60     70     60     70     60     70     60     70     80     70     80     50     80     70     80     70     80     70     90     80     70     90     80     70     90     80     100     70     90     80     100     70     90     90     90     90     90     90     90     90 <td>4</td>	4
	ELU83K	90	2
	EL 00 4 D	60       50       R     70       50       R     50       R     70       R     70       R     60       R     70       R     60       R     70       R     60       R     70       R     50       R     70       R     70       R     70       R     70       R     70       R     90       R     100       R     70       R     90       R     90       R     90       R     90       R     90       R     90	4
	ELU84K		2
	51 005 0	80	4
	ELU85K	100	2
Navara D23		70	4
	EL092R	90	2
	EL093R	90	4
		100	2
	EL094R	90	4
		100	2





Vehicle	Spring No.	U-Clip insert length (mm)	Quantity
	EL086R	60	4
		100	2
Triton MY15		60	4
Intoniwiti5	ELUOTR	100	2
	EL088R	70	4
		100	2
79 series	EL066R	88	4
		108	2
	EL079R	70	4
		100	2
		70	4
75 361163	LEOSON	100       EL087R     60       100     100       EL088R     70       100     88       EL066R     108       EL079R     70       100     100	2
	FL 081R		4
	LLOOIN	100	2
	EL082R	100	6
F-250 2008 on	EL077R	70	4
UAZ	EL078R	70	4

